

IMAGING

INSPECTION REPORT

108 CLIFTON BEACH DRIVE
PORT ST. JOE, FL 32456

06/14/2019



DRONE INSPECTION REPORT

06/14/2019

PROPERTY INFORMATION

CLAIM NUMBER
11216
TYPE OF LOSS
Wind
POLICY NUMBER
N/A
PHONE NUMBER
N/A
EMAIL ADDRESS
N/A



FLIGHT INFORMATION

ABOUT THIS REPORT




PHOTO LOCATIONS FROM SCAN

TOTAL IMAGES IN REPORT 57
DATE REPORT CREATED 06/14/2019

PAGE #
TOTAL NUMBER OF ANNOTATIONS 56
3

PILOT IN COMMAND
Brandon Thompson

DRONE ID NUMBER 07JDE2D00200JP
TOTAL FLIGHT TIME 00:16:13

START TIME 11:31 CDT -0500
END TIME 11:47 CDT -0500



PO001-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 15:49 CDT -0500

Additional Notes

06/14/2019 15:49 CDT -0500
Brandon Thompson
Front

PO002-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:03 CDT -0500

Additional Notes

06/14/2019 16:03 CDT -0500
Brandon Thompson
Front - impact to panel

PO003-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:04 CDT -0500

Additional Notes

06/14/2019 16:04 CDT -0500
Brandon Thompson
Front - impact to panel

PO004-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:05 CDT -0500

Additional Notes

06/14/2019 16:05 CDT -0500
Brandon Thompson
Front - Metal edges lifted

PO005-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:06 CDT -0500

Additional Notes

06/14/2019 16:06 CDT -0500
Brandon Thompson
Front - metal edge lifted

PO006-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:07 CDT -0500

Additional Notes

06/14/2019 16:07 CDT -0500
Brandon Thompson
Front - impact to panel

PO006-2 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:07 CDT -0500

Additional Notes

06/14/2019 16:07 CDT -0500
Brandon Thompson
Front - impact to panel

PO007-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:14 CDT -0500

Additional Notes

06/14/2019 16:14 CDT -0500
Brandon Thompson
Front - group of nails being driven
out.

PO008-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:16 CDT -0500

Additional Notes

06/14/2019 16:16 CDT -0500
Brandon Thompson
Front - Nails driven out.

PO011-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:16 CDT -0500

Additional Notes

06/14/2019 16:16 CDT -0500
Brandon Thompson
Front - Impact to panel.

PO012-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:19 CDT -0500

Additional Notes

06/14/2019 16:19 CDT -0500
Brandon Thompson
Front - nail driven out.

PO013-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:20 CDT -0500

Additional Notes

06/14/2019 16:20 CDT -0500
Brandon Thompson
Front - Impacts and nails driven out.

PO018-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:21 CDT -0500

Additional Notes

06/14/2019 16:21 CDT -0500
Brandon Thompson
Front - dent to ridge appears to be
from installation.

PO022-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:22 CDT -0500

Additional Notes

06/14/2019 16:22 CDT -0500
Brandon Thompson
Front - Impact to panel.

PO023-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:23 CDT -0500

Additional Notes

06/14/2019 16:23 CDT -0500
Brandon Thompson
Wind damage to siding

PO024-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:25 CDT -0500

Additional Notes

06/14/2019 16:25 CDT -0500
Brandon Thompson
Front and right slopes

PO025-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:25 CDT -0500

Additional Notes

06/14/2019 16:25 CDT -0500
Brandon Thompson
Right slope.

PO026-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:26 CDT -0500

Additional Notes

06/14/2019 16:26 CDT -0500
Brandon Thompson
Right - nail driven out.

PO027-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:27 CDT -0500

Additional Notes

06/14/2019 16:27 CDT -0500
Brandon Thompson
Right - scratches to panel.

PO028-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:28 CDT -0500

Additional Notes

06/14/2019 16:28 CDT -0500
Brandon Thompson
Right - impact to panel

PO029-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:29 CDT -0500

Additional Notes

06/14/2019 16:29 CDT -0500
Brandon Thompson
Front - Nail driven out.

PO031-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:30 CDT -0500

Additional Notes

06/14/2019 16:30 CDT -0500
Brandon Thompson
Right - Impacts to panel and nails
driven out.

PO032-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:32 CDT -0500

Additional Notes

06/14/2019 16:32 CDT -0500
Brandon Thompson
Right - Impacts and nails driven out.

PO033-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:32 CDT -0500

Additional Notes

06/14/2019 16:32 CDT -0500
Brandon Thompson
Right - Impacts to panel

PO034-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:33 CDT -0500

Additional Notes

06/14/2019 16:33 CDT -0500
Brandon Thompson
Right - impact to panel

PO036-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:34 CDT -0500

Additional Notes

06/14/2019 16:34 CDT -0500
Brandon Thompson
Right - scratches to panel.

PO037-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:35 CDT -0500

Additional Notes

06/14/2019 16:35 CDT -0500
Brandon Thompson
Right - impact to panel.

PO039-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:36 CDT -0500

Additional Notes

06/14/2019 16:36 CDT -0500
Brandon Thompson
Right - impacts to panel.

PO040-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:36 CDT -0500

Additional Notes

06/14/2019 16:36 CDT -0500
Brandon Thompson
Right - impact to panel.

PO041-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:38 CDT -0500

Additional Notes

06/14/2019 16:38 CDT -0500
Brandon Thompson
Right - impacts and nails driven out.

PO043-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:39 CDT -0500

Additional Notes

06/14/2019 16:39 CDT -0500
Brandon Thompson
Right - impacts to panel

PO044-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:41 CDT -0500

Additional Notes

06/14/2019 16:42 CDT -0500
Brandon Thompson
Right and rear slopes

PO045-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:42 CDT -0500

Additional Notes

06/14/2019 16:42 CDT -0500
Brandon Thompson
Rear slope

PO046-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:45 CDT -0500

Additional Notes

06/14/2019 16:45 CDT -0500
Brandon Thompson
Rear - nails driven out.

PO047-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:45 CDT -0500

Additional Notes

06/14/2019 16:45 CDT -0500
Brandon Thompson
Rear - nail driven out.

PO048-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:46 CDT -0500

Additional Notes

06/14/2019 16:46 CDT -0500
Brandon Thompson
Rear - impact to panel.

PO049-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:47 CDT -0500

Additional Notes

06/14/2019 16:47 CDT -0500
Brandon Thompson
Rear - impact to panel.

PO050-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:48 CDT -0500

Additional Notes

06/14/2019 16:48 CDT -0500
Brandon Thompson
Rear - impacts and driven out nails.

PO053-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:49 CDT -0500

Additional Notes

06/14/2019 16:49 CDT -0500
Brandon Thompson
Rear - impacts and nails driven out.

PO057-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:51 CDT -0500

Additional Notes

06/14/2019 16:51 CDT -0500
Brandon Thompson
Rear and left slopes

PO058-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:52 CDT -0500

Additional Notes

06/14/2019 16:52 CDT -0500
Brandon Thompson
Left Slope

PO059-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:53 CDT -0500

Additional Notes

06/14/2019 16:53 CDT -0500
Brandon Thompson
Left - impacts to panel.

PO060-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:54 CDT -0500

Additional Notes

06/14/2019 16:54 CDT -0500
Brandon Thompson
Left - impact to panel

PO061-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:55 CDT -0500

Additional Notes

06/14/2019 16:55 CDT -0500
Brandon Thompson
Left - impacts to panel.

PO062-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:56 CDT -0500

Additional Notes

06/14/2019 16:56 CDT -0500
Brandon Thompson
Left - nails driven out.

PO063-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:57 CDT -0500

Additional Notes

06/14/2019 16:57 CDT -0500
Brandon Thompson
Left - nails driven out and impacts.

PO064-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 16:57 CDT -0500

Additional Notes

06/14/2019 16:57 CDT -0500
Brandon Thompson
Left - impact to valley

PO065-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 16:58 CDT -0500

Additional Notes

06/14/2019 16:58 CDT -0500
Brandon Thompson
Left - impact to panel.

PO067-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 17:00 CDT -0500

Additional Notes

06/14/2019 17:00 CDT -0500
Brandon Thompson
Left - impact to panel

PO073-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 17:04 CDT -0500

Additional Notes

06/14/2019 17:04 CDT -0500
Brandon Thompson
Left - fascia damaged

PO074-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 17:05 CDT -0500

Additional Notes

06/14/2019 17:05 CDT -0500
Brandon Thompson
Left - impacts and nails driven out.

PO078-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 17:06 CDT -0500

Additional Notes

06/14/2019 17:06 CDT -0500
Brandon Thompson
Left - impacts to panel

PO081-1 WIND



Annotated by Brandon Thompson
on 06/14/2019 17:07 CDT -0500

Additional Notes

06/14/2019 17:07 CDT -0500
Brandon Thompson
Left - impact to ridge

PO082-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 17:08 CDT -0500

Additional Notes

06/14/2019 17:08 CDT -0500
Brandon Thompson
Left - impact to ridge

PO088-1 WIND




Annotated by Brandon Thompson
on 06/14/2019 17:08 CDT -0500

Additional Notes

06/14/2019 17:08 CDT -0500
Brandon Thompson
Lifted ridge

PO088-2 WIND



Annotated by Brandon Thompson
on 06/14/2019 17:08 CDT -0500

Additional Notes

06/14/2019 17:08 CDT -0500
Brandon Thompson
Lifted ridge